


Dri-Stor CABINET FILTER COMPONENTS

ANNUAL PM FILTER KIT

MODEL 40000PPFK

(2) HEPA Fan Pre-Filters, (2) HEPA Post-Filters, (2) O-Rings

Replacement every six months is recommended.



ANNUAL FILTER KIT FOR HEPA-ONLY CABINETS

MODEL 40000HEPAKIT

(2) HEPA Pre-Filters, (2) HEPA Post-Filters, (2) O-Rings,
(2) 40000EF (External Filter)

Replacement every six months is recommended.



SQUARE EXTERNAL FILTER FOR ENDOSCOPE CABINET

MODEL 40000EF

(1) White Square Fiber Filter with Frame

Replacement every six months is recommended.



ANNUAL FILTER KIT FOR 1 PUMP CABINETS

(FOR CABINETS WITH 10 SCOPES OR LESS)

MODEL 40000CPKIT-1

(2) HEPA Pre-Filters, (2) HEPA Post-Filters, (2) O-Rings,
(2) 40000EF (External Filters), (2) 40000CPHF

Replacement every six months is recommended.



REPLACEMENT MAIN HEPA FILTER

MODEL 40000MFF

(1) Main HEPA Filter Replacement

Replacement every two years is recommended.



ANNUAL FILTER KIT FOR 2 PUMP CABINETS

(FOR CABINETS WITH 11 SCOPES OR MORE)

MODEL 40000CPKIT-2

(2) HEPA Pre-Filters, (2) HEPA Post-Filters, (2) O-Rings,
(2) 40000EF (External Filters), (4) 40000CPHF

Replacement every six months is recommended.



IN-LINE FILTER PHD-02B

MODEL 40000CPHF

(1) Plastic Ball-Shaped Filter

Replacement every six months is recommended.

