


# Dri-Stor CABINET FILTER COMPONENTS

## ANNUAL PM FILTER KIT

MODEL 40000PPFK  
 2 HEPA Fan Pre-Filters, 2 HEPA Post-Filters, 2 O-Rings  
 Replacement every six months is recommended.



## ANNUAL FILTER KIT FOR HEPA-ONLY CABINETS

MODEL 40000HEPAKIT  
 2 HEPA Pre-Filters, 2 HEPA Post-Filters, 2 O-Rings,  
 2 40000EF (External Filter)  
 Replacement every six months is recommended.



## SQUARE EXTERNAL FILTER FOR ENDOSCOPE CABINET

MODEL 40000EF  
 1 White Square Fiber Filter with Frame  
 Replacement every six months is recommended.



## ANNUAL FILTER KIT FOR 1 PUMP CABINETS (FOR CABINETS WITH 10 SCOPES OR LESS)

MODEL 40000CPKIT-1  
 2 HEPA Pre-Filters, 2 HEPA Post-Filters, 2 O-Rings,  
 2 40000EF (External Filters), 2 40000CPHF  
 Replacement every six months is recommended.



## REPLACEMENT MAIN HEPA FILTER

MODEL 40000MFF  
 1 Main HEPA Filter Replacement  
 Replacement every two years is recommended.



## ANNUAL FILTER KIT FOR 2 PUMP CABINETS (FOR CABINETS WITH 11 SCOPES OR MORE)

MODEL 40000CPKIT-2  
 2 HEPA Pre-Filters, 2 HEPA Post-Filters, 2 O-Rings,  
 2 40000EF (External Filters), 2 40000EF (External Filter), 4 40000CPHF  
 Replacement every six months is recommended.



## IN-LINE FILTER PHD-02B

MODEL 40000CPHF  
 1 Plastic Ball-Shaped Filter  
 Replacement every six months is recommended.



Please Note: 40000CPKIT-3 and 40000CPKIT-4 were never launched.